

Moab District
Price River Resource Area
P. O. Drawer AB
Price, Utah 84501

RECEIVED

MAY 31 1985

DIVISION OF OIL
GAS & MINING

3400
(SL-062648)
(U-066)

Mr. Andrew C. King
Genwal Coal Company
P. O. Box 1201
Huntington, UT 84528

MAY 29 1985

Dear Mr. King:

A proposed minor modification of the R2P2 part of the approved mine plan for Genwal Coal Company's Crandall Canyon No. 1 Mine was submitted to this office on May 17, 1985. The proposal is for pulling pillars according to an approved MSHA roof control plan (Pillar Recovery Plan) being approved concurrently with this request. Mr. Allen Vance of my staff has reviewed the plan and has discussed the proposal with you. An inspection of the mine was made by him on May 23, 1985. During the inspection conditions were observed at the final mine limits in the Second South Panel of the mine prior to pulling pillars.

Accordingly, your proposal is approved subject to strict adherence to the procedures and conditions of the MSHA approval of the Pillar Recovery Plan.

If you have any questions, please contact Allen Vance at 637-4584.

Sincerely yours,

/s/ Leon E. Berggren
Area Manager

Enclosures (2)

- 1-Approved Minor Modification letter dated 5/17/85
- 2-Copy of Roof Control (Pillar Recovery Plan)

cc: DM, Moab (U-065) w/enclosures
SD, Utah (U-921) w/enclosures
OSM, Denver w/enclosures
✓DOCM, w/enclosures

ALVance:svo:5/28/85
6240 Mag